



Original Tree Position	Site	Original Tree Species	Confirm Reason for Removal	6 D's	Original Tree Easting	Original Tree Northing	Planting Notes	Replant Species	Replant Easting	Replant Northing
opposite/facing Clifford rd junction	PSALTER LANE	Tilia x europea	Damage to Surface	Damaging	433661.43	385511.22	TR: Replanting, Tilia 'Rancho' - Plant in new 800mm pit facing/opposite junction with Clifford Rd (same as felled tree)	Tilia cordata 'Rancho'	433661.54	385510.86
o/s 100	PSALTER LANE	Tilia x europea	Damage to Surface	Damaging	433689.33	385523.72	TR: Replanting, Tilia 'Rancho' - Plant in new 800mm pit o/s 100 (same as felled tree)	Tilia cordata 'Rancho'	433689.34	385523.52
At traffic light junction with Cowlishaw Rd, (next to 136)	PSALTER LANE	Tilia x europea	Damage to Surface	Damaging	433515.38	385444.43	TR: Replanting, Tilia 'Rancho' - Plant in new 800mm pit adjacent to pedestrian crossing (at junction Cowlishaw Rd, same as felled tree)	Tilia cordata 'Rancho'	433515.47	385444.59